



## Follow-up Service Inspection Report MH625441180830104920

INSPECTION DETAILS			
Date:	2018-08-30	File Number.:	MH62544
Responsible Office:	RTP	Volume:	1
Inspection Center:	111	CCN:	QGUZ
Product Type:	Life Safety & Security	UL Rep Name:	Michael Payne
Deliverable Type:	Listed	UL Rep ID:	13894
Party Site Number:	1699419	Subscriber Factory No.:	
Manufacturer Name:	Canada Rope and Twine Ltd	Factory Rep Name	Matthew Moore (1)
Manufacturer Address:	155 Bluewater Rd, Unit 103 Bedford NS	Factory Rep Phone:	902-835-2253
		Factory Rep Email:	matthew.m@canadarope.com
Nature of visit:	Regular Inspection	Sample Status:	Other
UL Marks Used?	No	UL Marks Removed?	No
Variation Notice Issued?	No		
Comments After Submission:			

PRODUCT DOCUMENTS/PRODUCTION READY VISIT			
Model	Product	Section	Multiple Listed
CRT-BWSTATIC11	Emergency Service Life Safety Rope	1	No

SAMPLE DOCUMENTS			
If samples are required to be sent to ULI Laboratory, indicate below. If required samples are not sent, explain in the Comments area.			
No Samples			
Additional Comments	IPI conducted.		

In addition to the requirements specified in the applicable UL Services agreement and Follow-Up Service Procedure, UL further defines responsibilities, duties and requirements for both manufacturers and UL representatives in the document titled "UL Mark Surveillance Requirements" that can be located at [www.ul.com/fus](http://www.ul.com/fus), and in accordance with the applicable terms and conditions of the document at [www.ul.com/responsibilities](http://www.ul.com/responsibilities). Manufacturers without Internet access may obtain the current versions of these documents from their local UL customer service representative or UL field representative.